

General Environmental Incident Summary

Incident: 3839 **Notice:** 7/30/2015 1038 **Occurred:** 7/17/2015 1500

DEM Incident No:

No Further Action: ☒

Responsible Party: Harvest Honey Inc.

County: Burleigh

Twp Rng Sec Qtr: 142 80 34 SE SE SE

Lat Long + Method: 47.07101 -100.79530 Interpolation from map

Location Description: Harvest Honey, Inc., 400 240th Avenue Northwest, Baldwin, ND

Submitted By Info: Kirsten Dickhut
Braun Intertec - Consultant
1341 S 20th St
Bismarck ND 58504

Received By Info:

Contact Info: Roberta Verhoek
225 CR 402
Danbury ND 77534

Affected Medium: 02 - water

Near. Occupied Bldg: 500 Feet

Type of Incident: Groundwater Sample Confirmation During Phase II Investigation

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Diesel-contaminated surface water/groundwater

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Braun Intertec conducted a soil and surface water investigation of a burn pit on the site following a Phase I investigation recommendations. Surface water was found to have a concentration of approximately 5 ppm DRO. Soil in the sidewalls at the soil/water interface found to be clean.

Risk Evaluation:

None

Potential Env. Impacts:

Groundwater could be impacted, but impacts are likely limited.

Action Taken/Planned:

Burn pit is not being used. Braun Intertec is investigation methods of remediation. Appropriate remedial action will be taken, pending coordination with NDDOH. Copy of report is available upon request.

Wastes Disposal Location:

Depends on type of remedial action selected.

Other Agencies Involved:

Updates

Date: 7/30/2015 ***Status:*** Reviewed - Assigned to NDDEQ Division

Author: Suess, Bill

Notes:

Carl Anderson has spoken with the consultant and will be reviewing the work plan. The Groundwater Protection Program has the lead on this.

Updated Volume: None at the time of this update